Cleanup Site Details

9/18/2015

PIERCE COUNTY

SITE ID:	OCCIDENTAL CHEMICAL CORP		Clea	FS ID: 1212					
	Alternate Name(s): OCCIDENTAL CHEMICAL CORP, PIONEER AMERICAS INC, PIONEER AMERICAS LLC, PIONEER CHLOR ALKALI CO INC								
LOCATION:			WRIA: 10	Lat/Long:	47.279	-122.407	View Vicinity Map		
Address:	605 ALEXANDER AVE			Township	Range	Section	Legislative District: 27		
	TACOMA	98421-4209		21N	3E	27	Congressional District: 9		
STATUS:	Cleanup Started		Rank:		<u>View Site Web Page</u>		View Site Documents		
	Responsible Unit: Southwest	Site Manager:	Wilhelm, Leon		Statute: MTCA				
	Is Brownfield?	Has Enviro	nmental Covenant?		Is PSI Site? `	Yes			
	NFA Received?	NFA Date:	NFA Date: NFA Reaso						

ASSOCIATED CLEANUP UNIT(s)

cuID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
11272	OCCIDENTAL CHEMICAL CORP	Sediment	Ecology-supervised or conducted	Cleanup Started		
11410	OCCIDENTAL CHEMICAL CORP	Upland	Ecology-supervised or conducted	Cleanup Started		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received			3/1/1988			Wilhelm, Leon
CleanupSite MilestoneTyp		Ecology Remedial Investigation and/or Feasilibity Study	Planned			Agreed Order	PLP	Leja, Stan
CleanupSite MilestoneTyp		Ecology Remedial Investigation and/or Feasilibity Study	In Process	2/1/2005			EPA	Wilhelm, Leon

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Corrosive Wastes	С		С			
Halogenated Organics	С		С			
Metals Priority Pollutants				С		
Non-Halogenated Solvents	С	С		С		
Polychlorinated biPhenyls (PCB)				С		

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level

S - Suspected

R - Remediated

RA - Remediated-Above

RB - Remediated-Below



Cleanup Site Details

CleanupSiteDetails2014